



# Irrigation Repair

Project Address: **Commons Dr. - 1131**  
Project Name: **Nepenthe Association**  
On-Site Location: **Elmhurst 613 - Zone 5 – See attached photos**

Carson Landscape Industries agrees to provide labor and materials to perform the following services.

### Work Description

Controller E  
Station 65: Repair and relocate (1) broken lateral line in root infested area.

### Materials

(12 ft.) 1” PVC Pipe  
Misc. Irrigation Parts and Hardware

**Total Labor and Materials: \$370.00**


**TERMS:** Payment in full is due upon completion of the work. A finance charge of 1.5% per month will be added to the unpaid balance after 30 days. In the event legal action is taken to collect on a past due account, the debtor agrees to pay all collection costs including interest, attorney’s fees and court costs. Any alteration or deviation from the above involving extra cost of material or labor will only be executed upon written orders for same, and will become an extra charge over the sum mentioned in this contract. All agreements must be in writing. Our workers are fully covered by workers compensation and our firm is covered by liability insurance. **This proposal may be withdrawn by us if not accepted within 30 days.**

### **Carson Landscape Industries**

*Contractor’s License No. 470283*  
9530 Elder Creek Rd.  
Sacramento, CA 95829-9306  
Tel: 916-856-5400 • Fax: 916-856-5410  
Email: olopez@carson1975.com

Nepenthe Association  
1131 Commons Drive  
Sacramento, CA 95825-  
Tel: 916-929-8380  
Email: Nicole.Marks@fsresidential.com

By: **Oscar Lopez (by GO)**  
Name: Oscar Lopez  
Title: Account Manager  
Date: 3/4/2025

By:   
Name: Nicole Marks Courtenay Delfin  
Title: President  
Date: 4/2/2025

