




Nepenthe Owners Association  
Zone 2—Controller B

*broken  
retrofit line*

Irrigation Controller Map  
12/1/2021



*broken lateral  
by tree*

*broken retrofit  
line*

*broken  
retrofit line*

Carson Landscape Industries

