



Irrigation Repair

Project Address: **Commons Dr. - 1131**
Project Name: **Nepenthe Association**
On-Site Location: **See attached map & photos**

Carson Landscape Industries agrees to provide labor and materials to perform the following services.

Work Description

- Zone 3 Station #66 – Repair (1) broken Netafim line by Swarthmore – 2312
- Zone 7 Station #2 – Repair (2) broken Netafim lines by University – 1425

Materials

- Misc. Irrigation Parts and Hardware

Total Labor and Materials: \$140.00


TERMS: Payment in full is due upon completion of the work. A finance charge of 1.5% per month will be added to the unpaid balance after 30 days. In the event legal action is taken to collect on a past due account, the debtor agrees to pay all collection costs including interest, attorney’s fees and court costs. Any alteration or deviation from the above involving extra cost of material or labor will only be executed upon written orders for same, and will become an extra charge over the sum mentioned in this contract. All agreements must be in writing. Our workers are fully covered by workers compensation and our firm is covered by liability insurance. **This proposal may be withdrawn by us if not accepted within 30 days.**

Carson Landscape Industries and The Grove

Contractor’s License No. 470283 & 1034968
9530 Elder Creek Rd.
Sacramento, CA 95829-9306
Tel: 916-856-5400 • Fax: 916-856-5410
Email: olopez@carson1975.com

Nepenthe Association
1131 Commons Drive
Sacramento, CA 95825-
Tel: 916-929-8380
Email: Abigail.Helman@fsresidential.com

By: Oscar Lopez (by KM)
Name: Oscar Lopez
Title: Operations Manager
Date: 3/20/2026


By: 
Name: Abigail Helman
Title: _____
Date: _____

Nepenthe Owners Association
Zone 3—Controller C

Irrigation Controller Map
12/1/2021

CARS
IN
Landscape Industries
Creating an Environment of Quality since 1975

*broken netafin
line.*



Property of
Landscape Inc
Zone 4

